

Consequences of Stack Effect



Indoor Air Quality Problems

MOLD

ODORS

ALLERGENS

Excessive
Moisture in
Basement &
Crawlspace



PESTS



STRUCTURAL DECAY

DRY ROT/RUST



Foundation Problems